

# SERVICE BULLETIN

GO-KART #4  
APRIL 25, 1994

## BRACKET, BRAKE CALIPERS

### SYMPTOM

The brake caliper bracket lifts up off it's mounts. This is caused by the manufacturing of slots in the bracket. The updated bracket are now made with round mount holes.


### CORRECTIVE ACTION

Remove old caliper bracket and install updated part supplied at no charge.


### PARTS INFORMATION

Parts stock has been exchanged and there is no change to the part number.  
Part # 01087

OLD →



NEW →



If you have any questions concerning this service bulletin please call technical service at 1-800-854-3140