

SERVICE BULLETIN

February 26, 1996

Thunder-03

Cowling Update

AFFECTED MODELS

ThunderBolt go-karts sold between December 1, 1995 to January 6, 1996

SYMPTOM

A gap developing over time in-between Cowling [A] and Body [B].

CORRECTIVE ACTION

Install new Cowling.

Warranty: The normal warranty applies. Updated parts are ship with this bulletin at no charge.

