

SERVICE BULLETIN

AUGUST 1995

GO-KART FRAME UPDATE

AFFECTED MODELS

Go-Karts equipped with enlarged hole for brake line.

SYMPTOM

Excessive stress causing frame rail to crack.

CORRECTIVE ACTION

Install frame brace.

Frame, Brace Left **Part#008111**

Updated parts will be sent at no charge.

Call (800) 854-3140 or (503) 363-7533 if you have any



2315 Pringle Road SE
Salem, Oregon 97302
(800) 854-3140
FAX (503) 363-7885



Inside: Go-Kart Muffler Service Bulletin..