

*****GO-KART BULLETIN*****

Warning: Fuel tank vent being plugged or restricted resulting in fuel vapor expansion, distorting fuel tank.

This can cause the tank to bulge and in extreme cases contact the muffler protector. If this should occur the plastic fuel tank can become softened and could result in a rupture.

Check fuel tank caps for proper venting on a regular and frequent basis. Beware of any bulging of all plastic compound fuel tanks, regardless of application.