


SERVICE BULLETIN

June 12, 1998

PRODUCT UPDATE: MUFFLER, HEAT SHIELD



MODELS INVOLVED

All F16 go-karts equipped with Muffler Heat Shield [7]

SYMPTOM

The Muffler Heat Shield breaks where it attaches to reduction gear case. (see reference [A])

CORRECTIVE ACTION

Install Update immediately.

Ref#	Part#	Qty	Description
1	002961	3	Screw, 10-24 x1 Phil Pan Head SS
2	11130	1	Bracket, Motor Cover (F-16)
3	11151	1	Rubber, Anti-Vibration Motor Cover (F-16)
4	00297	3	Nut, 10-24 S/S Nylock
5	00251	2	Spacer, Honda Handle Bar
6	00115	2	Screw, 5-0.8 x 30mm P/P/H M/S Zinc
7	11112	1	Cover, Engine 9hp Silent F16