



J&J Amusements, Inc.
4897 Indian School Rd NE
Salem OR 97305
U.S.A
Phone: 1-503-304-8899
Website: www.jjamusements.com
E-mail: info@jjamusements.com

Bulletin No: 22KARTGUARDBODY
Release Date: 10/1/2022
Effective Date: 10/1/2022
Supersedes: N/A
Supplement: 11KARTHAIRBODY
Completion Date: See text
Page: 1 of 1

NOTIFICATION

Ride Manufacturer: J&J Amusements, Inc.

Affected Production Dates:
Pre-November 2022

Ride Name: Go-Kart

Affected Serial Nos: ALL

Model: Sidewinder, Sidewinder Double, Scorpion, King Scorpion, Can Am, Sidekick
(Honda GX-240 & GX-270 engines only).

Abstract of Issue:

Installation of the axle drive cover guard and the engine guard assemblies to be performed by the owner at the owners expense.

Reason for Release:

To reduce the risk of unrestrained long hair or loose clothing becoming entangled in rotating parts.



NOTE:

THE ONLY WAY TO ELIMINATE THE RISK OF LONG HAIR OR LOOSE CLOTHING ENTERING ROTATING PARTS IS TO BE SURE LONG HAIR IS SECURED ABOVE THE SHOULDER FOR THE DURATION OF THE RIDE CYCLE. LOOSE CLOTHING MUST BE SECURE AND CONTAINED WITHIN THE SEATING AREA FOR THE DURATION OF THE RIDE. IF THE GUEST SHOULD REFUSE TO COMPLY, THEY SHOULD NOT BE ALLOWED TO OPERATE OR BE A PASSENGER IN THE GO-KART.

Action to be Taken:

Installation of J&J engine guard assembly and axle drive cover guard assembly.

Engine guard assembly part # 1-61-A0013



Axle drive cover guard assembly part # 1-60-A3020